

# Oil Field Environmental Incident Summary

**Incident:** 20161031072900

**Date/Time of Notice:** 10/31/2016 07:29

**Responsible Party:** Hess ND Pipelines LLC

**Well Operator:**

**Well Name:**

**Field Name:** BEAVER LODGE

**Well File #:**

**Date Incident:** 10/28/2016

**Time Incident:** 13:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 95

**Sec:** 20

**Qtr:** SE NW

**Location Description:** The area surrounding an abandoned 24 inch Gas Gathering Line

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Troy Brunsell  
3015 16th Street South, Suite 20  
MINOT, ND 58701

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.6 Mile

**Distance Nearest Water Well:** 0.6 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

**Spilled Units**

**Recovered Units**

**Followup Units**

**Oil**

**Brine**

**Other**

**Description of Other Released Contaminant:**

Hydrocarbon contaminated soil was found. The release quantity is unknown at this time.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

At this time, there are no known immediate risks associated with the contaminated soil discovered.

**Areal Extent:**

**Potential Environmental Impacts:**

The extent of the impacts cannot be determined until the area is further excavated.

**Action Taken or Planned:**

The landowner has been notified by the Hess Land Team. The area will be further excavated to identify the source and determine a release quantity.

**Wastes Disposal Location:** All waste will be disposed of at an approved waste disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 10/31/2016 **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a pipeline leak, impacted topsoil in Williams County. Further follow-up is needed.

---

**Date:** 11/7/2016 **Status:** Correspondence

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received an email and map from the company contact showing the location of the release. Map shows GPS coordinates at 48.323317, -102.928141. Email and map added to incident folder. More follow-up needed.

---

**Date:** 11/10/2016 **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 11/09/16 at 10:30 a.m. Excavated area is directly east and adjacent to valve at 48.323347,-102.928738. Chemical/gas odors present. Area excavated is approximately 8 feet deep and 5 X 8 feet wide. Follow-up needed.